

ELONGATED WITH A FILE)

2) MAKE SURE TO TURN CAM COUNTER CLOCKWISE BY PHILLIPS
DRIVER HOLDING TUBE WITH FINGERS AS FAR AS IT WILL GO

BEFORE RE-ASSEMBLING OF HANDLE TO PREVENT MIS-POSITIONING OF CAM. (SEE FIG. 1 AND FIG. 2)




FIG. 2