



9990

Fire Door Top Gap Solution — *Up To 90 Minutes*

PRODUCT CUT SHEET


**UL Certified for Door Top
Gaps — Measuring up to 1/2".**



- ▶ 90-Minute Rated — for Use on UL10B and UL10C Wood or Hollow Metal Fire Doors
- ▶ No Need to Move Hardware at the Top of the Door
- ▶ Works on doors with Parallel arm closers
- ▶ Patent Pending
- ▶ Available in 36" and 48" Lengths
- ▶ Brushed Stainless Steel
- ▶ End Caps Furnished Standard
- ▶ Non-Handed

PRODUCT CONSISTS OF:

- + #304 Brushed Stainless Steel Flat Plate - Pull Side
- + #304 Brushed Stainless Steel Intumescent Cap — Push Side
- + #304 Brushed Stainless Steel End Caps
- + #6 X 3/4" Stainless Steel SMS Furnished



PROJECT:

SUBMITTED BY:

DATE:

NOTES:

NGP-GAP-9990-PCS-1119-A